

How to get an **EXPOSURE CONTROL PLAN** from a safety consultant

are required to comply with the * NEW OSHA SILICA DUST STANDARD. YOUR PLAN SHOULD DESCRIBE how to keep the amount of respirable silica dust on a jobsite BELOW THE PERMISSIBLE EXPOSURE LIMIT (PEL).

Fortunately, getting a plan is straightforward, and THE AMERISAFE GROUP CAN ASSIST YOU EVERY STEP OF THE WAY.

3 SIMPLE STEPS for Receiving a Plan

ASK FOR ASSISTANCE

Help can be requested in one of two ways:



Call Amerisafe

If no one is available to answer, they will typically respond within 24 hours!



Contact James Hardie

A technical services rep can put you in touch with Amerisafe, or you can fill out a form to request help on the James Hardie Silica Resource Center. Just visit: jameshardiepros.com/safety

CONNECT WITH AMERISAFE



Amerisafe will call you once they've processed your request for assistance.



They will gather the information needed to prepare your plan and answer any additional questions.

GET A CUSTOM EXPOSURE CONTROL PLAN



Amerisafe will determine an exposure control plan that works specifically for your jobsite and help you incorporate the best practices for cutting James Hardie products.



Once your plan is ready, Amerisafe will deliver it along with materials to assist you in training your crews.

PUTTING YOUR PLAN INTO ACTION

Your custom exposure control plan will provide a simple process to help prepare your business for the OSHA silica dust standard, but you can always contact Amerisafe or James Hardie if you need help with implementing any of the steps.



For further assistance, call the Amerisafe Group at:

844-295-6709

To access the James Hardie Resource Center, visit:

jameshardiepros.com/safety

For training support, call James Hardie technical services at: 800-942-7343